

Major experience of repair in 2017 (Type of repair)

2018/3/30

contents of repair	place
Erosion resistance	Ishikawa
Tip crack (lightning)	Ishikawa
Down conductor repair	Ishikawa
Down conductor repair	Ibaraki
Erosion resistance + erosion control paint application	Wakayama
Erosion resistance + erosion protection seat installation	Ishikawa
Erosion resistance	Yamaguchi
Erosion resistance + tip crack	Tottori
Crack Repair of trailing edge	Nigata
Crack Repair of trailing edge	Mie
Crack Repair of trailing edge	Aomori
Crack Repair of trailing edge	Erosion Improvement
Transverse crack repair	Ishikawa
Transverse crack repair	Aomori
Erosion resistance	Aomori
Tip crack (lightning)	Saga
Inside of the blade (manhatch) repair	Akita
Inside of the blade (manhatch) repair	Yamagata
Opening repair of trailing edge	Yamagata
Opening repair of trailing edge	Akita
Tip crack + trailing edge + down conductor repair (lightning)	Shimane
Tip crack + trailing edge (trailing edge) opening repair (lightning)	Yamagata
Opening repair of trailing edge	Yamaguchi
Tip crack (lightning)	Akita
Erosion resistance (on the ground)	Chiba
Down conductor repair	Yamaguchi