Maior	rotoronco	lict of	inspection	of blada
IVIAIUI	reference	IISL UI	IIISDECTION	

2018/3/30

Inspection detail	Place	Wind turbine manufacturer • Blade manufacturer
UT inspection (above ground)	Ishikawa	LM
Appearance inspection/Conductor test	Shizuoka	Enercon
Appearance inspection/Conductor test	Chiba	LM
Appearance inspection/Conductor test	Ishikawa	LM
Appearance inspection/Conductor test	Tottori	LM
Appearance inspection/Conductor test	Saga	LM
Appearance inspection/Conductor test	Aomori	LM
Appearance inspection/Conductor test	Niigata	LM
Appearance inspection/Conductor test	Akita	LM
Appearance inspection/Conductor test	Niigata	Hitachi
Appearance inspection/Conductor test	Chiba	GE Almero
Appearance inspection/Conductor test	Chiba	GE Tecsis
Appearance inspection/Conductor test	Aomori	Hitachi
Appearance inspection/Conductor test	Wakayama	Hitachi
Appearance inspection/Conductor test	Saga	GE Tecsis
Appearance inspection/Conductor test	Akita	Hitachi
Appearance inspection/Conductor test	Ishikawa	GE Almero
Appearance inspection/Conductor test	Aichi	Vestas
Appearance inspection/Conductor test	Tottori	Mitsubishi
Appearance inspection/Conductor test	Shimane	Vestas
Appearance inspection/Conductor test	Shimane	GE Noi
Appearance inspection/Conductor test	Akita	LM
Appearance inspection/Conductor test	Yamagata	LM
Appearance inspection/Conductor test	Aichi	Hitachi
Appearance inspection/Conductor test	Fukui	Hitachi